

# GENERAL DELIMING

## Tools Needed

- Clean White Wiper
- Non-Abrasive Pad
- Delimer Spray Bottle


## Product Needed

DCT  
Delimer Packet




**FREQUENCY OF CLEANING:** Use as needed at closing time. Areas that may need general deliming are food warmers, sink areas, around spigots, and faucets.

**SPECIAL DIRECTIONS FOR THIS TASK:** If sensitivity to cleaning solutions is a concern, wear disposable gloves.




### STEP 1

- Empty contents of one packet of DCT Delimer into a 12-ounce Delimer spray bottle.
- Fill bottle with warm water.
- Place sprayer onto bottle and tighten.
- Shake gently until Delimer is dissolved.




### STEP 2

- Spray generous amounts onto surface to be delimed.




### STEP 3

- Allow product to sit on surface for at least 15 minutes.



### STEP 4

- Re-wet surface with another spray application of Delimer.



### STEP 5

- Wipe area with a wiper. If mineral build-up is not removed, lightly scrub the area with a non-abrasive pad.
- Rinse area with water.

**NOTE:** Repeat Steps 2 through 5 if necessary until any and all built-up mineral deposits are removed.



### STEP 6

- Wash hands before returning to service area.